Unit Job History

MnDOT

Report Printed: 05/21/2020 10:04:59 By User: CARL1KIM

Unit No: 92634 - 1992 ALPHA 1000

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
01/30/2003 00:00:00	0	0	121227	22-49	Install Mounted Equipment	02/18/2003 13:37:15	MOD333	F	DON	272.02
01/06/2010 07:00:03	0	0	276176249	32-51-006	DO NOT USE Safety Equipment	02/08/2010 14:25:28	MOD000	N	DON	12,068.14
02/09/2009 09:25:38	0	0	276140076	34-51-006	Remove Safety Equipment	02/10/2009 09:24:31	MOD000	O	DON	343.16
02/04/2009 13:05:41	0	0	276139640	38-34	Repair/Repla Lighting System	02/05/2009 13:30:10	MOD000	O	DON	531.67
10/10/2018 08:27:00	0	0	276512215	38-34-006	Repair/Repla Special Warning Lights/Dev	10/10/2018 12:00:55	MGA000	O	DON	202.55
06/15/2016 08:09:48	0	0	276425728	11-65	Diagnos/Test Hydraulic Systems	06/20/2016 16:13:52	MGA000	O	DON	74.66
06/15/2016 08:09:48	0	0	276425728	32-65-022	DO NOT USE VALVE - FLOW CONTR	06/20/2016 14:55:56	MGA000	F	DON	207.86
05/11/2016 09:34:03	0	0	276422559	32-65-020	DO NOT USE VALVE - CONTROL	05/16/2016 12:10:58	MOD777	O	DON	202.79
07/22/2014 08:11:57	0	0	276351865	38-34-006	Repair/Repla Special Warning Lights/Dev	07/22/2014 10:26:45	MOD777	O	DON	126.47
04/13/2010 09:12:59	0	0	276187977	22-51-006	Install Safety Equipment	04/13/2010 11:56:04	MOD000	O	DON	257.38
09/27/2007 11:23:29	0	0	276080900	32-34-004	DO NOT USE Clearance, Marker, Interio	09/28/2007 08:53:25	MOD333	F	DON	5.56
09/27/2007 11:23:29	0	0	276080900	38-35-001	Repair/Repla CONTROL	09/28/2007 08:52:05	MOD333	O	DON	359.59
06/01/2017 05:39:50	0	0	276461112	11-65	Diagnos/Test Hydraulic Systems	06/01/2017 08:03:59	MGA000	O	DON	137.33
06/01/2017 05:39:50	0	0	276461112	32-65-007	DO NOT USE HOSES & FITTINGS	06/01/2017 09:05:10	MGA000	F	DON	58.61
11/17/2008 11:50:31	0	0	276128944	38-35-002	Repair/Repla CONTROL AND MONITC	11/19/2008 14:23:46	MOD333	O	DON	358.89
04/14/2008 14:21:30	0	0	276106196	38-34-006	Repair/Repla Special Warning Lights/Dev	04/18/2008 14:44:44	MOD333	O	DON	1,674.69
09/17/2004 10:47:44	0	0	192671	38-34	Repair/Repla Lighting System	09/17/2004 15:27:06	MOD333	O	DON	275.77

Unit No: 92634 **Count: 17** **17,157.14**

Total Job Count and Repair Cost: **Count**: **17** **17,157.14**

Unit Job History

Report Title: UNITJOBHISTDISP - Unit Job History V17.0

Report Author: FleetFocus M5

File Path: C:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\T79

Data Extracted: Thu May 21 2020 10:04:59 **Report User:** CARL1KIM

TZ: Central Standard Time

DLL Version: 2018.08.01

Report Comments: 5/31/06 - Focus No 7069 6/14/06 - Focus No 7996 & No 3053 7/12/06 - Focus No. 5392 03/28/07 - Focu 13916 07/02/07 - Focus No. 15696 10/08/07 - Focus No. 16414 02/08/08 - Focus No. 18696 01/21/09 - No. 22842 12/10/09 - Focus No. 24193 07/06/09 - Focus No. 25012 08/15/10 - Focus No. 31840 06/23/ Focus No 28649 09/06/11 - Focus No. 36445 11/11/11 - Focus No. 35887 06/04/12- Focus No. 39905 07/03/12 - Focus No. 39906 08/06/15 - FMV-3791
08/24/15 - FMV-3590 09/21/15 - FMV-4217 04/10/17 - FMV-9446

Parameters and Selection Filters

First Grouping: NONE

Second Grouping: NONE

Third Grouping:

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: {view_unit_wo.unit_no} = '92634' //Q=